

15142	CORNELL 11	<i>Free Form</i>	1943	ELEM TRAINER	
REGISTRATION No.	MAKE & MODEL		YEAR	TYPE	MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Lined area for handwritten remarks.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 233D — 8M-1-43 (5029) H.Q. 885 — E-233

AIRCRAFT RECORD CARD

FIRST ENTRY AT	<i>No 4 TC</i>	DATE	<i>21 9 43</i>	TRANSFER ORDER No.	<i>2279</i>
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>31.11.44</i>	<i>Stored Reserve #3TC</i>	<i>T.O. 14569</i>			
<i>15.1.45</i>	<i>Stored Reserve Co. 1 A.C.</i>	<i>T.O. 17061 (103)</i>			
<i>20.4.45</i>	<i>No. 1 A.C.</i>	<i>T.O. 12406</i>			
<i>27.9.45</i>	<i>Apdul - 1 A.C.</i>	<i>T.O. 15014</i>			
<i>10.9.46</i>	<i>Apdul on 6 Rd St Johns</i>	<i>T.O. MC 12673</i>			
<i>10.9.46</i>	<i>Mr C.M. McCabe</i>	<i>T.O. MC 12470</i>			
	<i>Office Foreign Liquidation Com.</i>				
	<i>40 Bevilacqua Road</i>				
	<i>Niagara Falls N.Y.</i>				

REMARKS:
27.9.45 - Time since new - 751.55
" " Overhaul
Location - #3 BEMU. (E. St. John)

ENGINE TYPE	<i>RANGER 6-440-C5</i>	UNITS	AIRSCREW TYPE (CODE)	REF. No. <i>21930/1033</i>
BATCH No.	<i>QUAN. IN BATCH USA 139</i>	LEDGER FOLIO	<i>713-Misc-USA 139</i>	SPECIFICATION No.
REGISTRATION No.	<i>15142</i>	MAKE & MODEL	<i>CORNELL II</i>	YEAR
				<i>1943</i>
			<i>ELEM TRAINER</i>	MANUFACTURERS No.