

965

CORNELL I

505D

1943

ELEM TRAINER

FH 965

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
13.7.43		Mid West atc Wpg					
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
1	C 2	Davidson, Sask		23 EFTS 159	8.3.43				
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Plane - 1050 hrs, a/c not suitable for use. engine overhaul required. engine working during flight. Pilot's report - 8.3.43

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME T. O. No.

ENGINE/S (QUOTE SERIAL NOS.) T. O. No.

AIRSCREW/S (QUOTE SERIAL NOS.)

ACCESSORIES

REMARKS: EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT 1-5-43 DATE 20-2-43 TRANSFER ORDER No. 5762

Initial Entry Below TRANSFERS Calgary TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
11.3.43	# 2 J.L. 6/3	T.O. 6078			
15.7.44	Mid West etc Ltd	T.O. D373			
20.11.44	APDAL # 21.C	T.O. 17270			
1.12.44	APDAL - No. 2 A.O.	T.O. 17327(13)			
6-12-45	Special on 155E121	5000128			
20.9.46	47 Mar. 1946	T.O. 13495			

REMARKS

Hrs :- (Lease Lend)
 Since New :- 1275:55
 " o/haul :- NA
 Location :- 205. 6 H.U. Neepawa Man

ENGINE TYPE RANGER 6-440-05	UNITS 1	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH USA 119	LEDGER FOLIO 713-38-USA 119	SPECIFICATION No.
REGISTRATION No. 965	MAKE & MODEL CORNELL I	YEAR 1943	TYPE ELEM TRAINER
			MANUFACTURERS No. FH 965