

1409

EXPEDITER II

1944

T E TRANSPORT.

HB 238 (43-35745)

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
17 Aug 49	repair overhaul transmission	J R. 611	W 086-77			22/10/49	MBA
22 Oct 49	to suit Special P. 12-12 recondition	Frank Perry					
23 Oct 49	mod to spec P. 12-12	MBA	W 501628				
18-5-51	repair, recondition overhaul to spec RM 129	MBA	W 51861 CD W 376816			28 Apr 52	TC
10 May 54	5 retrofit motor	MBA					
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

21 Aug 47 - 1st flight T.S.M. 932.30, T.S.O. 70. Delivered - U.P. (4 passengers only)
 30 Nov 47 - 2nd flight T.S.M. 1018.35, T.S.O. 71. A. Co. continuation of flight. Delivered. U.P.
 31 Mar 48 ✓ 1074.00 ✓ ✓ ✓ ✓ ✓
 31 Mar 49 - 3rd flight T.S.M. - 1379.05, T.S.O. 71 A

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. NO.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 293D — 6M-1-43 (3029) H.O. 885 — E-283

AIRCRAFT RECORD CARD

FIRST ENTRY AT # *H.T.C.* DATE *15.5.44* TRANSFER ORDER NO. *13370*

TRANSFERS

TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>1.13.44</i>	<i>2 Air Command</i>	<i>To 17328(15)</i>	<i>9/9/54</i>	<i>TC</i>	<i>QT0511</i>
<i>1.12.44</i>	<i>3 TC</i>	<i>To 17397</i>	<i>Feb 1/56</i>	<i>WR New Lincoln Park</i>	<i>QT0687</i>
<i>15.1.45</i>	<i>No. 1 A.C.</i>	<i>T.O. 17864(E3)</i>	<i>Feb 1/56</i>	<i>SR New Lincoln Park</i>	<i>QT0687</i>
<i>15 July 46</i>	<i>9 T Group</i>	<i>To MC 12331</i>	<i>27 May 56</i>	<i>TC (2 AFS Sankaton)</i>	<i>QT0515</i>
<i>Page 46</i>	<i>AW Transport Command</i>				
<i>17 Aug 49</i>	<i>J.R. 6 RD</i>	<i>To AMC 12240</i>			
<i>22 Oct 49</i>	<i>Navis (MacDonald Bros)</i>	<i>To AMC 12341</i>			
<i>27 June 50</i>	<i>Write off & replace</i>	<i>To 12341</i>			
<i>28 June 52</i>	<i>TC (AFS back)</i>	<i>To 1079</i>			
<i>10 May 54</i>	<i>10TS4 (MBA)</i>	<i>QT0-1106</i>			

REMARKS: USA No. 43-35745

LEASE END.

Can Equip C10858 #E2848
*Lib 136 Misc 858**211659*
*211739**20752*
211029

ENGINE TYPE	WASP R985-AN-14B	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.	QUAN. IN BATCH	USA 835	LEDGER FOLIO	714-Misc-USA 835	SPECIFICATION No.		
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE	MANUFACTURERS No.			
1409	EXPEDITER # <i>1731</i>	1944	T.E. TRANSPORT.	HB 238 (43-35745)			

1409

EXPEDITER
3TWASD
R985-AN14B

43-35745 2.

216757 11150

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
2 May 56	QTO-515	TC 2AFS Saskatoon			
6 Jan 59	QTO 955	BAW ER			
6 Jan 59	QTO 955	TC 2AFS Saskatoon			
6 Jul 59	TC QTO 33	TC CFS Saskatoon			
4 Sep 62	TC QTO 6	TC CFS Saskatoon			
2 Dec 63	TC QTO 28	TC 1AFS Phoenix			
5 June 64	QTO 304	Diagnosed 1005750 Saskatoon			
5 Aug 64	QTO-459	Adapted to 1005750 1005750 UE 2692			
6 Aug 68	WAM 113	LTDB - sold to: Hamilton Aircraft Company Inc. c/o 266915 9 Jul 68 6501 St. Park Ave (PO Box 11427) Tucson, Arizona 85706 U.S.A.			

OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
6 Jan 59	955	BAW 772810	for reconditioning to RR 2-12

THE OFFICE SPECIALTY MFG. CO., LTD. 26346 L

1003T515-7340 28 Nov 63. SPIC completed