

4538

FINCH II

SOLD

1940

ELEM TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
26.5.42	Time exp	Cul 91				20.7.42	#320
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
13.12.41	"C"	Kindness Int.	1615	7EFTS SA 108	19/12	1st Lt. A. W. Miracle			
27.3.42	"C"	Windsor Aerod.	1415	7EFTS SA 35	30/3	RAC CA Gosham			
26.4	"B"	London Airport	0925	3EFTS T 90	26/4				
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

~~Re-acc 3. Engine installed 1380/6042~~

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT		DATE	TRANSFER ORDER No.		
Wood Reserve London		16/11/10	2104		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
12/19/43	H. L. ...	T.O. 2317			
26.5.42	Cdr G. Hamilton	TO CH 71			
20.7.	#37C	T.O 1906			
28.9.43	#9 B.D (W. Res)	To 2,1332			
11.4.44	APDAL #3 T.O.	T.O. 12442			
17.10.44	WAR ASSETS CORPORATION FOR CHARLES H. BABB & CO.	T.O. 16663			

REMARKS

Hrs:- Since New: 1485:35  
 " Overhaul: 1274:20  
 Cost.

Location:- 9 R.D St. Johns Que B.C.A.T.P.

ENGINE TYPE	KIRNER 35R	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH	1 P 4	LEDGER FOLIO	1200-38-3	SPECIFICATION No.	
REGISTRATION No.		MAKE & MODEL	SOLD	YEAR	1940	TYPE	ELEM TRAINER
						MANUFACTURERS No.	