

OVERHAUL DATA							
DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD									
DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
29.5.41	"A"	Windsor, Ont	0945	#7EFTS, 3A29	29/5	LAC H.C. Taylor		Spares produce	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

The Decl: The 9c involved in this accident was first reported as 4704 - letter from #I.C. file 1100-47-4, 8/1/41 confirms 9c as 4707
 Eng installed 1352/6014
 Total Flying Time: - 448²⁵ hrs (auth. IIC letter, 926 22-1, d/22/19/42)

