

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
11.9.42	1	June exp	lean	Airwarp			
	2					2.11.42	F3TC SR
	3						
	4						
	5						
	6						
	7						
	8						
	9						
	10						
	11						
	12						

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
18.10.41	1	H. Eugene Aerod	1140	13 EFTS, SE 160	18/10	Sgt. H. M. Moore			
31.10	2	H. Eugene Aerod	1100	13 EFTS SE 174	31/10	LAC J. L. Sullivan	Solo		
24.3.42	3	H. Eugene Aerod	2130	13 EFTS SE 37	25/3	Sgt. L. Taylor	4		
19.4.	4	St. Justin Que	1330	13 EFTS SE 61	20/4	LAC J. Reah	Solo		
	5								
	6								
	7								
	8								

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 1: - a/c landed too close behind and crashed into a/c 4641.
 Re acc 2. Eng installed Kenner BSR 1756/6 hrs
 Re acc 3 a/c 4781 taxied into rear of a/c 4780 which was parked near night flying taxiport. Failed to see a/c in time.
 7.9.43. Allotted to # 9 R.O.W. Res for write off action

