

3534 (42-5046)

NORSEMAN IV (U.S. ARMY AIR CORPS.) RETURNED

1942

S E TRANSPORT.

(WRITE-OFF)

REGISTRATION No.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
5.8.42	B	St. Hubert	1515	1WS.F.S. A1602	6/18	Pt J. Leroux	5	write-off	
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. Acc. 1. While landing, gust of wind made pilot make heavy landing. Engine caught fire damaging front of cabin & rear of engine.

REMARKS:

This A/C completely demolished in crash at St Hubert.
Que. 6.8.42.

RECORD OF WRITE-OFF							
APPLICATION RC'D FROM	DATE	FILE NO.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
#9 R.D. (E107) Serial # 41	30.9.42	1038AK-3534	5.11.42	#3 JC	#9 R.D.	5.11.42	E1053
DISPOSAL PARTICULARS							
AIRFRAME							T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)							T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)							
ACCESSORIES							
REMARKS:							EFFECTIVE DATE WRITTEN-OFF
							36-1-42

AIRCRAFT RECORD CARD					
FIRST ENTRY AT	DATE	TRANSFER ORDER NO.			
no. 11 Tech. Detach.	26.1.42	13595			
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
26.1.42	U.S. Army Air Corps Dayton, Ohio	TO 14060			
16.6.42	#3 T.C.	TO 1311			
2.11.42	Write-off	T.O. E1053			

REMARKS loaned to U.S. Army Air Corps To. 14060 permanently - Replacement
16/6/42:- THIS A/C ONE OF NORSEMAN BEING REPLACED BY U.S. ARMY AIR CORPS.

ENGINE TYPE	UNITS	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE
3534 (42-5045)	NORSEMAN IV (U.S. ARMY AIR CORPS, B. 3534)	1942	S E TRANSPORT.
			MANUFACTURERS No. (WRITE-OFF)