

**OVERHAUL DATA**

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

**ACCIDENT RECORD**

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
9.5.41	1 "A"	Seamich, B.C.	1415	Pak Bay, sA368	9/5	Boyd Dawson	1		
14.12.41	2 "C"	Wuden road	0920	19EFTSS A21	14/12	AC BR Lowland Solo			
8.2.42	3 "A"	Falk Horn.	920	19EFTSS A9	8/2	RAC Sheer R.J. Solo		Write-off	
4									
5									
6									
7									
8									

B. S. LTD.

**AIRCRAFT RECORD CARD**

PAT'D 1920

**REMARKS**

Re acc. 2 :- Engine installed - Spray Motors - no. 87140/1318.  
 Re acc. 3 :- Engine installed 87140/1318. Planes collided.  
 Pilots jumped with parachutes. Other ac # 4962  
 Tiger Moth.

