



PURPOSE OF FLIGHT:

Night Circuits and landings.

TECHNICAL OFFICER'S REPORT:

Nil

TBG/PCT/USG/XGM

NATURE OF ACCIDENT:

Pilot of A/C FW279 taxied off runway (12) almost opposite taxi post as he was attempting to pass to port of an a/c already parked just short of taxi post A/C ran into shallow ditch resulting in collapse of nose oleo leg. Sky overcast. Slight precipitation - visibility good.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

10. Bad Ground

SECONDARY OR CONTRIBUTORY FACTORS:

34. U/C Strain.

ACTION TAKEN:

Nil