

ACCIDENT CLASSIFICATION

UNIT **161 Sqdn. (BR)** COM. **E.** PLAC. **In front of No. 4 Hangar** DATE **19-1-45** TIME **17.15 APT**
at Yarmouth, N.S., H.Q. FILE **1100-97-41**


A/C TYPE **CANSO "A".** NO. **9741** CRASH CAT. **"C"** S.E. M.E. DAY NIGHT
X X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
ROBINSON, J.N.,	F/L	J10563	P	Uninj.	NO. 4735	DATE 20-1
FUGLEM, M.O.,	F/O	J43727	2 P.	Uninj.		
PANKIN, P.,	F/O	J46834	Nav.	Uninj.	D 14 (REVISED)	
LAMBERT, A.L.,	WO2	R186154	WAG	Uninj.		
COOMBS, H.G.,	F/S	R187689	WAG	Uninj.	NO.	CHECKED
POMERLEAU, G.L.,	F/S	R62736	Eng.	Uninj.		
MILL, J.D.,	F/L	J5091	Pass.	Uninj.	2	
HARROW, P.G.,	F/L	J11582	Pass.	Uninj.		
TORGERSON, E. R.,	F/O	J50091	Pass.	Uninj.		

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
P & W. Twin	P.A262440/9922	N11					
Vesp SIC38	S.A262441/9923	N11					
			92	246	10	632	126
			45	40	11	9	100

ACCIDENT CLASSIFICATION

COMMAND
 MONTH
 STAGE OF FLIGHT
 FORCED LANDING
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STAT'RY
 PATL
 INJ.
 INJURY



PURPOSE OF FLIGHT:

Radio range cross country ex. Yarmouth, Ellisville and return.

NATURE OF ACCIDENT:

Plank covering over w/c pits on taxi strip in front of No. 4 Hangar failed to support weight of a/c while taxiing over them. A/C wheels fell through into pits and damage was done to the aft portion of the step on the hull by coming into contact with the concrete.

CLASSIFICATION:

10. Bad Ground

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

M11 TBC/XCR

COURT OF INQUIRY OR INVESTIGATING OFFICER'S

FINDINGS:

SUMMARY No.

ACTION TAKEN:

M11

COOPER, A. J.	44393	P/O	Pass.	Undf.
SEWELL, W. O.	66684	P/O	Pass.	Undf.
LANE, W. A.	82126	P/S	Pass.	Undf.
SMITH, J. W.	82108	Sgt.	Pass.	Undf.
PEARSON, P. H.	189071	P/O	Pass.	Undf.